

Safety related modules / components

ID-no.	Type	BOM	HW Rev.	Report-no.	Validity
090820	SAFE-DELAY / ESM-BT421	090820 / B	I / 1223	968/M 280.04/26	valid
090819	SAFE-DELAY / ESM-BT411	090819 / B	I / 1223	968/M 280.04/26	valid
090818	SAFE-DELAY / ESM-BT401	090818 / B	I / 1223	968/M 280.04/26	valid
090068	SAFE-DELAY / ESM-BT421P	090068 / B	I / 1223	968/M 280.04/26	valid
090067	SAFE-DELAY / ESM-BT411P	090067 / B	I / 1223	968/M 280.04/26	valid
090081	SAFE-DELAY / ESM-BT421-20S	090081 / C	I / 1223	968/M 280.04/26	valid
090077	SAFE-DELAY / ESM-BT411-20S	090077 / C	I / 1223	968/M 280.04/26	valid
090079	SAFE-DELAY / ESM-BT401-20S	090079 / C	I / 1223	968/M 280.04/26	valid
090082	SAFE-DELAY / ESM-BT421P-20S	090082 / C	I / 1223	968/M 280.04/26	valid
090078	SAFE-DELAY / ESM-BT411P-20S	090078 / C	I / 1223	968/M 280.04/26	valid
090080	SAFE-DELAY / ESM-BT401P-20S	090080 / C	I / 1223	968/M 280.04/26	valid
090094	SAFE-DELAY / ESM-BT421-50S	090094 / C	I / 1223	968/M 280.04/26	valid
090087	SAFE-DELAY / ESM-BT411-50S	090087 / C	I / 1223	968/M 280.04/26	valid
090072	SAFE-DELAY / ESM-BT401-50S	090072 / C	I / 1223	968/M 280.04/26	valid
090095	SAFE-DELAY / ESM-BT421P-50S	090095 / C	I / 1223	968/M 280.04/26	valid
090088	SAFE-DELAY / ESM-BT411P-50S	090088 / C	I / 1223	968/M 280.04/26	valid
090086	SAFE-DELAY / ESM-BT401P-50S	090086 / C	I / 1223	968/M 280.04/26	valid

The content of this Revision List has been agreed between Manufacturer and Test Institute.

Revision:

Date	Rev.	Description / Changes	Author
2026-04-30	1.0	Initial creation, based on Report-No.: 968/M 280.04/26	Ih/A-FS&CS